

3D Laser Scanning

- FARO 3D Laser Scanner with 8-axis
- Comparison reports between the tool model and damaged tooling
- The arm can scan to an accuracy of 46 µm over 2.5m, however, we have conducted tests and have received results of sub 10 µm.